



STEPPER motor was 500 pulse/revolution  
 1 Revolution = 25mm on machine  
 Y Travel = 350mm or 14 revolution or 7000 pulse  
 X travel = 510 or 21 revolution or 10500 pulse  
 20KHz pulse = 0.5 second move

J6 HEAD DRIVER VALVE

